



Wick

LIGHTING THE WICK FOR THE FIRST TIME:

Push out about ½" of the wick and light.

EXTINGUISHING THE WICK:

Extinguish the wick by blowing out the flame. Extinguishing the wick by retracting it into the tube and smothering the flame will cause excessive wax buildup inside the tube.